

Hygrometers – Dew Point

Introduction

The measurement of atmospheric moisture is achieved in various ways. The Center® range of digital Humidity Meters use a Thermistor to measure the temperature and a Ceramic Sensor for the Humidity measurement. A Datalogging version is available and details can be found in Section 6.

Features

- Dual or Triple Display (depending on model)
- Auto Power Off
- Hold Function
- Max/Min Function
- Resolution 0.1% RH, 0.1 °C



316

317

Models Available & Specifications

Model	316	317
Humidity Range & Accuracy	0/100 % RH ±3% RH	0/100 % RH ±2.5% RH
Temp Range & Accuracy	-20/60 °C ±0.8 °C	-20/60 °C ±0.8 °C
Type K Sensor & Accuracy	No	No
Dew Point	Yes	Yes
Wet Bulb	Yes	Yes

Postal Address

Homersham Ltd
PO Box 280
Christchurch 8140
NEW ZEALAND

Phone: 03 3588309
Phone: 0800 659888

Website: www.homershams.co.nz

Delivery Address

Homersham Ltd
3 Homersham Place
Burnside
Christchurch 8053
NEW ZEALAND

Fax: 03 3582516
Fax: 0800 659777

E-mail: info@homershams.co.nz

132

